PG:67-27

# Dairy Industry Bungalow II (Building 160)--Beltsville Agricultural Research Center

Location: Beltsville, MD (Prince George's County)

Date of Construction: c. 1933

Access: Public

Building 160 was constructed in the Dairy Area of the Beltsville Agricultural Research Center, one of the earliest developed areas of the site. The bungalow, constructed by the Bureau of Dairy Industry, has been used as housing for Bureau employees since its construction in the early 1930s.

Maryland Historical Trust Inventory Form
Maryland Comprehensive Historic Preservation Plan Data
Building 160 - P.G. #67-27
Beltsville Agricultural Research Center
Prince George's County, Maryland

## HISTORIC CONTEXT

# MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

Geographical Organization: Western Shore

Chronological/Developmental Periods: Industrial/Urban Dominance

Prehistoric/Historic Period Theme(s): Agriculture

Resource Type:

Category: buildings

Historic Environment: rural

Historic Function(s) and Use(s): domestic

Known Design Source: none

## ADMINISTRATIVE/EXECUTIVE SUMMARY

In connection with the Beltsville Agricultural Research Center (BARC) Master Plan, the Agricultural Research Service (ARS) initiated procedures to comply with Section 110 of the National Historic Preservation Act of 1966 (as amended). In October 1995, Robinson & Associates, Inc., an architectural history and historic preservation consulting firm, was retained as consultants to conduct a survey of residences on the BARC property. A total of 18 residential buildings were identified by ARS for inclusion in the survey, which is being completed in phases. This report presents an assessment of the National Register eligibility of one of the buildings in the fourth phase of evaluation.

#### **METHODOLOGY**

Soon after the initiation of the project, a windshield survey of 18 residences at the Beltsville Agricultural Research Center, including Building 160, was conducted. A subsequent site visit to Building 160 enabled closer investigation of both the interior and exterior of this residence; photographs were taken at this time.

Research regarding Building 160 was conducted at the National Archives and Records Administration at College Park and the Library of Congress. Previous work by Robinson & Associates on the history of BARC (Robinson & Associates, Inc., "Beltsville Agricultural Research Center, Phase III Report," December 1995; "Preliminary Historic Context Statement, North Farm, Beltsville Agricultural Research Center," November 1994) provided information on the acquisition and development of the North Farm.

Maryland Historical Trust Inventory Forms were prepared for each residence, based on the requirements specified in the Guidelines for Completing the Maryland Inventory of Historic Properties Form.

## **EVALUATIONS OF INDIVIDUAL ELIGIBILITY**

Following is an evaluation of Building 160 (the Dairy Industry Bungalow II), which was considered under Criteria A, B, and C at the local and national levels of significance. The relevant National Register criteria, as listed in the *National Register Bulletin 16* (U.S. Department of the Interior, National Park Service, Interagency Resources Division), read as follows:

The quality of significance in American history, architecture, archeology, and culture is present in districts, sites, buildings, structures, and objects that possess integrity of location, design, setting, materials, workmanship, feeling, and association, and:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period, or method of construction or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components

may lack individual distinction; . . .

D. has yielded, or is likely to yield, information important in prehistory or history.

## Dairy Industry Bungalow II - Building 160

#### Criterion A

Built as a residence for employees of the Bureau of Dairy Industry at BARC, this house is a typical example of a 1920s bungalow, at which no significant events are known to have occurred. It does not meet Criterion A.

#### Criterion B

Building 160 does not appear to have significance under Criterion B. There is no evidence that any residents occupying Building 160 were associated with significant contributions to local history or BARC history.

#### Criterion C

Building 160 is a typical example of a bungalow from the early decades of the twentieth century. The style is common in the United States and in Prince George's County, and is part of the design aesthetic used by the Bureau of Dairy Industry in the late 1920 and 1930s. Building 160 features craftsman details that complement the rural farm setting. Although the house does not appear to be altered and retains much of its original integrity, it is not eligible under Criterion C.

#### Criterion D

Building 160 was not evaluated for archeological significance.

## **EVALUATION AS PART OF A DISTRICT**

Building 160 is one of a collection of buildings developed by the Bureau of Dairy Industry at BARC. The Bureau created a cohesive group of buildings by utilizing the same materials and compatible designs for all of their buildings. They selected a Craftsman style, visible in many buildings, including barns, laboratories, and residences. Although the Dairy Area exhibits some qualities typical of a district, such as a consistent design aesthetic and a physical relationship between the functional buildings of the site, further study will have to be undertaken to determine the possibility of a district. This work is will be undertaken by Robinson & Associates, Inc. in the future. Further evaluation will reveal whether this house is a contributing element of such a district.

Survey No. P.G. #67-27				
Ma DOE _	gi No. yes	no		

# Maryland Historical Trust State Historic Sites Inventory Form Maryland Inventory of Historic Properties

1. Name	
Historic Name Dairy Industry Bungalow II	
Common Name and Building Number Building 160	_
2. Location	
Street and Number Beltsville Agricultural Research Center	
City, Town Beltsville	Congressional District
State and Zip Code MD 20705	County Prince George's
3. Classification	
Category     Ownership     Status       District     X Public     Occupied       X Building(s)     Private     X Unoccup       Structure     Both     Work in F       Site     Public Acquisition     Accessible       Object     In Process     Yes: Restr       Being Considered     X Yes: Unr       No	Progress Educational Residence Entertainment Religious icted X_ Government Scientific
4. Owner of Property	
Name U.S. Department of Agriculture	
Street & Number 10300 Baltimore Avenue	Telephone No.: (301) 504-5187
City, Town Beltsville	State and Zip Code MD 20705
5. Location of Legal Description	
Courthouse, Registry of Deeds, etc. Prince George's County Courth	nouse Liber# 390 Folio# 160
Street & Number Main Street	
City, Town Upper Marlboro	State and Zip Code MD
6. Representation in Existing Historic Survey	_ Yes <u>X</u> No
Title	
Date	Federal State CountyLocal
Depository for Survey Records	

PG:67-27

/	•				
	,				
7	,				

7. Descripti	ion		-	Survey No. P.G. #61-27
Condition Excellent Good Fair	Deteriorated Ruins Unexposed	X Unaltered Altered	X Original Site Moved	

SEE CONTINUATION SHEETS

Maryland Historical Trust Inventory Form
Continuation Sheet. Section 7: Description
Dairy Industry Bungalow II - Building 160 - P.G. #67-27
Beltsville Agricultural Research Center
Prince George's County, MD

Section 7 Page 1

#### Overview

Building 160 is located within the Dairy Area of the Beltsville Agricultural Research Center (BARC), one of the earliest areas developed by the Department of Agriculture at the site. The house was constructed by the Bureau of Dairy Industry (BDI) c. 1933 and is located on Powder Mill Road. Building 160 is adjacent to Building 159, another bungalow built by the Bureau of Dairy Industry. The house is currently unoccupied.

# **Exterior Description**

Building 160 is a one-story, Craftsman-style, poured concrete bungalow with a low hipped roof with overhanging eaves. The exterior of the building has been covered with stucco. The roof, which is covered with composition roll material scored to look like shingles, is punctuated by two small triangular central dormers, one on the north elevation and one on the south. Each dormer has a three-light horizontal window. A stuccoed interior chimney protrudes from the roof on the east elevation.

The principal (north) facade is three bays wide, each of which is delineated by four engaged piers. The upper half of each bay is highlighted by a tripartate fenestration pattern. Located in the center bay, the front door is paneled and has a six-light window. The original door is obscured by a modern metal storm door. An Arts and Crafts-style, vertical, four-light tympanum is placed over the door, and narrow ten-light vertical sidelights flank the door. The two outer bays each feature a large, central, one-over-one, double-hung window, again flanked by narrow ten-light vertical sidelights. A projecting beltcourse emphasizes the level of the raised basement, and aligns with the top step of a flight of five concrete stairs leading to the front door.

The east elevation has three, one-over-one, double-hung windows with simple concrete sills.

The south elevation has a small recessed entry porch at the rear door. A flight of five concrete steps leads to the porch, and the porch and stairs are enclosed by a metal railing. A pier supporting a corner of the hipped roof is located in the southwest corner of the building. Two, large, one-over-one, double-hung windows with simple concrete sills complete this elevation. The raised basement is punctuated by a small single-paned basement window, located adjacent to the rear flight of stairs. A wooden bulkhead door which leads to the basement is centered beneath the two larger windows.

The west elevation has two, one-over-one, double-hung windows with simple concrete sills. The recessed rear entry porch and the pier supporting the roof are also visible from this elevation.

#### Interior Description

A center hall which leads to a bathroom at the rear is entered from the enclosed front porch. A large front room which runs east-west is divided by columns on recessed, raised, paneled blocks. The east end of the room features a brick fireplace surround with brass detailing. Two additional rooms are located on the east

Maryland Historical Trust Inventory Form
Continuation Sheet. Section 7: Description
Dairy Industry Bungalow II - Building 160 -- P.G. #67-27
Beltsville Agricultural Research Center
Prince George's County, MD

Section 7 Page 2

side of the house. Rear doors open into the kitchen in the southwest corner of the house. Tall doors with transom lights are featured throughout the house.

# Landscaping

Several mature trees and miscellaneous shrubbery surround the house. It is situated on Powder Mill Road, a prominent curvilinear road which runs east-west through BARC.

8. Significar	ıce							Sı	rvey No. P.G. #67-27
Period  _ Prehistoric _ 1400-1499 _ 1500-1599 _ 1600-1699 _ 1700-1799 _ 1800-1899 X 1900 Com	Areas of Signi Archeology-Pro Archeology-Hi X Agriculture Architecture Art Commerce munications	ehistoric	Con Econ Edu Eng Eng Expl	nmunity Pl servation nomics cation incering loration/Se	ttlement	Law Liter Milit Mus	ature ary ic osophy	Theat	Religion Science Sculpture X Social/Humanit er Transportation (specify)
Specific Dates		Archit	ect				Builde	r	Area
Applicable Cri	teria:	_A	B	C	D	• -			· · · · · · · · · · · · · · · · · · ·
Applicable Exc	ception	A	B	C	D	E	F	G	
Level of Signif	icance	Nati	onal	Sta	ite		_ Loca	al	

SEE CONTINUATION SHEETS

Maryland Historical Trust Inventory Form Continuation Sheet. Section 8: Significance Building 160 — P.G. #67-27 Beltsville Agricultural Research Center Prince George's County, Maryland

Section 8 Page 4

#### Overview

Building 160 was built c. 1933 as part of a New Deal expansion effort of the Bureau of Dairy Industry. The Bureau designed and built residences for some of its employees during this expansion. The materials and overall design used in the construction of Building 160 are similar to those used by the Bureau of Dairy Industry's engineers for barns, laboratories, and related buildings in the Dairy Area.

## The Bureau of Dairy Industry

The Dairy Division was created in 1845 as a division of the Bureau of Animal Industry. The Dairy Division moved to Beltsville in 1910, when the Bureau of Animal Industry purchased 475 acres of land in Beltsville, allocating 190 of those acres to the Dairy Division. In 1924, the Dairy Division became a separate bureau of the Department of Agriculture.

The Bureau of Dairy Industry only had one regulatory function, which was inspecting factories that produced renovated butter.<sup>1</sup> However, the Bureau conducted research on dairy cow breeding, diseases, and nutrition, with the ultimate goal being increased milk production from the herd. Product research included methods to more efficiently manufacture dairy products and new ways to use by-products of manufacturing processes. The results of this research was shared with farmers across the country in the forms of pamphlets and other written materials.<sup>2</sup>

Buildings located in the Dairy Area are among some of the oldest at BARC, due to the Dairy Division's early occupation of the site. Several buildings, including the Main Nutrition Barn (Building 167), the Mess House (Building 173), and the Open Cow Shed/Milk House (Building 170) date from the 1910s.

During the early New Deal efforts, \$158,000 was spent on the construction of nine new buildings in the Dairy Area. The principal building among these was Building 157, a laboratory and dairy products building equipped to conduct experiments related to the manufacture of dairy products on a large scale. Building 160 is located opposite South Dairy Road from Building 157, directly adjacent to Building 159.

#### **Building 160**

Building 160 is one of two bungalows (the other is Building 159) constructed along Powder Mill Road by the Bureau of Dairy Industry during New Deal expansion efforts. This housing was used to accommodate employees who lived on site. Documents located at the National Archives indicate that Building 160 was occupied in the mid-1930s by Ray H. Smith, Assistant Dairy Husbandman at BARC at the time. Approximately \$300 per year was deducted from his annual salary of \$2,900 to cover the cost of rent, heat,

<sup>&</sup>lt;sup>1</sup>Preliminary Inventory of the Records of the Bureau of Dairy Industry, October 1965, RG 152.

<sup>&</sup>lt;sup>2</sup>Information taken from Robinson & Associates, *Phase III 100% Submittal for Beltsville Agricultural Research Center*, December 1995.

Maryland Historical Trust Inventory Form Continuation Sheet. Section 8: Significance Building 160 -- P.G. #67-27 Beltsville Agricultural Research Center Prince George's County, Maryland

Section 8 Page \$5

and lighting costs.<sup>3</sup> At the time, Building 160 was described as a "semi-bungalow-concrete" with six rooms and a bath. Bungalows made excellent employee housing, as these typically small homes were economical to build and to maintain. Today, the residence retains many of its original building materials and features.

<sup>&</sup>lt;sup>3</sup>Report prepared in response to request from the Secretary of Agriculture ca. July 1935. RG 152, Entry 170, Box 7.

# 9. Major Bibliographical References

Survey No. P.G. #67-27

#### SEE CONTINUATION SHEETS

# 10. Geographical Data

Verbal Boundary Description

The boundary of the site follows Powder Mill Road to the north, and South Dairy Road to the west. On the east and south, the boundary is defined as extending 50 feet beyond the perimeter of the house itself.

# 11. Form Prepared by

Name/Title Regina Arlotto, Heather Ewing, Judith Robinson, Architectural Historians

Organization Robinson & Associates, Inc. Date November 30, 1996

Street & Number 1909 Q St., NW #300 Telephone (202) 234-2333

City or Town Washington, D.C. State 20009

Concurrence of State Preservation Officer

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

Return to:

Maryland Historical Trust

DHCP/DHCD

100 Community Place

Crownsville, Maryland 21032-2023

(410) 514-7600

Maryland Historical Trust Inventory Form Continuation Sheet. Section 9: Bibliography Dairy Industry Bungalow II - Building 160 - P.G. #67-27 Beltsville Agricultural Research Center Prince George's County, Maryland

Page 5

# **Bibliography**

Gowan, Alan. The Comfortable House: North American Suburban Architecture, 1890-1930. Cambridge, MA: MIT Press, 1986.

Maryland-National Capital Park and Planning Commission. *Illustrated Inventory of Historic Sites*. July 1993.


McAlester, Virginia and Lee. A Field Guide to American Houses. New York: Alfred A. Knopf, 1994.


National Archives Records Administration, Record Group 152, Records of the Bureau of Dairy Industry, Entry 170. Washington, D.C.

Phillips, Steven J. Old House Dictionary: An Illustrated Guide to American Domestic Architecture, 1600 to 1940. Lakewood, CO: American Source Books, 1989.

Robinson & Associates, Inc. *Phase III Submission: Cultural Resources Report Historic Overview, Beltsville Agricultural Research Center, Beltsville, Maryland.* Prepared for the U.S. Department of Agriculture, Agriculture Research Service, December 1995.

Robinson & Associates, Inc. Preliminary Historic Context Statement, North Farm, Beltsville Agricultural Research Center, Beltsville, Maryland. Prepared for the U.S. Department of Agriculture, Agriculture Research Service, November 1994.







PAIRY BUNGALOW II (BUILDING 160)

PG \* 67-27

BELTSVILLE AGRICULTURAL RESEARCH CENTER

BELTSVILLE MD

PHOTO BY REGINA ARLOTTO, JULY 1996

NEGATIVE AT MD SHPO

NORTH (FRONT) FACADE LOOKING SOUTH

I OF 5



PAIRY BUNGALOW I (BUILDING 160)

PG \*67-27

BELTSVILLE AGRICULTURAL RESEARCH CENTER
BELTSVILLE, MP

PHOTO BY REGINA ARLOTTO, JULY 1996

NEGATIVE AT MD SHPO

SOUTH FACADE LOOKING NORTH

2. OF:5



PAIRY BUNGALOW II (BUILDING 160) PG = 67-27 TELTS VILLE AGRICULTURAL RESEARCH CENTER BELTSVILLE, MP PHOTO BY REGINA ARLOTTO, JULY 1996 NEGATIVE AT MP SHPO INTERIOR, VIEW OF FIRST FLOOR HALL LOOKING NORTH 30F 5



PAIRY BUNGALOW II (BUILDING 160)
PG #67-27
BELTSVILLE AGRICULTURAL RESEARCH
CENTER
BELTSVILLE, MP
PHOTO BY REGINA ARLOTTO, July 1996
NEGATIVE AT MP SHPO
INTERIOR, VIEW OF FIRST FLOOR HALL
LOOKING SOUTH
4 OF 5



PAIRY BUNGALOW I (BUILDING 160)

PG #67-27

BELTSVILLE AGRICULTURAL RESEARCH CENTER

BELTSVILLE MP.

PHOTO BY REGINA ARLOTTO, JULY 1996

NEGATIVE AT MP SHPO

INTERIOR, VIEW OF FIREPLACE LOOKING WEST

5 OF 5